


Bruhat Bangalore Mahanagara Palike

Inspection Report

1	Name of Work	Desilting of drains at JP park roads from Mathikere bus stand to Mohankumar nagara
2	Administration Approval and Date	EE/RRND/AS/251/2011-12, Dated: 01-07-2011
3	Technical Sanction Estimate No. & Date	EE/RRND/TS/251/2011-12, Dated: 01-07-2011
4	Estimate Amount	Rs. 5.00 lakhs
5	Job Code No	017-12-000006
6	P-Code	P0546
7	Agreement No & Date	EE/RRND/AGR/461/2012-13, dated: 27-11-2012
8	Work Order Number & Date	EE/RRND/Wo.No/461/2012-13, dated: 27-11-2012
9	Contract Amount as per Agreement	Rs. 5,24,591=00
10	Bill Amount	Rs. 5,24,591=00
11	B.R. No & Date	151/13-14 dated: 22-06-2013
12	Agency	V. Prakash
13	M.B. Number & Page No. of Measurement Recordes	Xerox copy of MB No. 81, Page No 8009 to 8010
14	Date of Inspection	11/10/2015
15	Enclosures	(1) Sketch showing the location of site (Area Map) (2) ~~Four~~ ^{Four} numbers of Photos taken during Inspection
16	Inspection Report	The above job has been inspected by me along with the concerned officials. The items involved in the above work is satisfactory for measurements. As such the photos taken during the execution of the work has been scrutinized and local engineers have been made. It appears that the above work has been carried out. This work has been carried out more than two years back. This has a reference to the Xerox copy of MB No 81


 EE(RRND) RR NAGARA
 EXECUTIVE ENGINEER


 (R. SATHYANARAYANA)
 INSPECTION REPORT OFFICER



Rajeshwar
 Executive Engineer
 Rajarajeshwarinagar Division
 Bruhat Bangalore Mahanagara Palike
 Bangalore 560 075

11/10/2015
 R. SATHYANARAYANA
 INSPECTION OFFICER